


1. Approving National Aviation Authority / Country LUFTFAHRT-BUNDESAMT / Germany	<b>AUTHORIZED RELEASE CERTIFICATE</b> <b>JAA FORM ONE</b>	3. Form Tracking. No. 24428-01 / 17071
---	--	---

4. Approved Organisation Name and Address:	<b>Goodrich Hella Aerospace Lighting Systems GmbH</b> Bertramstr. 8 D 59557 Lippstadt	5. Work Order / Contract / Invoice R 1934/KL/02
--	--	--

6. Item	7. Description	8. Part No.	9. Eligibility (*)	10. Qty	11. Serial- / Batch No.	12. Status / Work
1	Flight Crew Reading Light Cockpit-Leseleuchte	2LA 004 626-00	Various	1	1596	REPAIRED+MODIFIED

13. Remarks Repaired and tested in compliance with CMM-No:33-11-11 - Housing 403361-15, Light Head 403357-05 and Ball Cap 403694-00 defective. Replacement of a/m parts Modification to Amd. A Functional test satisfactory	Issue: 2  Modified to Amendment: A
--	--

14. Certifies that the items identified above were manufactured in conformity to:  <input type="checkbox"/> approved design data and are in condition for save operation <input type="checkbox"/> non-approved design data specified in block 13	19. <input checked="" type="checkbox"/> JAR 145.50 Release to Service <input type="checkbox"/> Other Regulation specified in block 13  Certifies that unless otherwise specified in block 13 the work specified in block 12 and described in block 13, was accomplished in accordance with JAR-145 and in respect to that work the items are considered ready for release to service
---	--

15. Authorised Signature	16. Approval/Authorisation Number	20. Authorised Signature 	21. Certificate/Approval Ref No. LBA.0117
17. Name	18. Date (d / m / y)	22. Name Wolfgang Walter                      LBA5328	23. Date (d / m / y) 11.03.2003

User/Installer Responsibility

NOTE: 1. It is important that the existence of the Document alone does not automatically constitute authority to install the part / component / assembly.  
 2. Where the user / installer works in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1 it is essential that the user / installer ensures that this / the Airworthiness Authority accepts parts / components / assemblies from the Airworthiness Authority specified in block 1.  
 3. Statement 14 and 19 do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

# Defect Report

GRH Part No.	Description	Customer Part No.	Serial No.	Quantity	
2LA 004 626-00	Flight Crew Reading Light		1596	1	
Work Order / Contract No.	GRH-Reference-No.	Incomming Date	Quotation Date	Release Date	Redelivery Date
R 1934/KL/02	24428-01 / 17071	16.12.2002	06.03.2003	06.03.2003	11.03.2003

**Customer Name:** Contact Air  
**Aircraft Model:** 2LA 004 626-00  
**Aircraft Registration No.** D-AFKL  
**Aircraft Delivery Date:** . .  
**Installation Date:** . .  
**Removal Date:** . . .  
**TSN:** 26477  
**TSO:** 0  
**Work Status:** REPAIRED+MODIFIED  
**Modification Status:**  
**Modified to:** A  
**Poduced [MM/YYYY]:** 09/1990

No

**Customer Findings:** Switch broken

**Supplier Findings and/or Actions:** Repaired and tested in compliance with CMM-No: 33-11-11  
 Issue: 2  
 - Housing 403361-15, Light Head 403357-05 and Ball Cap 403694-00 defective.  
 Replacement of a/m parts  
 Modification to Amd. A  
 Functional test satisfactory

**Customer/GRH-Findings:** Repair Shop finds any failure: Yes

**Customer Findings confirmed:** Yes

**Preventive Action:** None.

Departm.	Person of Contact	Telephone	Fax	e-Mail	Signature
V21	Anke Huth	0049294138 2832	0049294138 8155	anke.huth@goodri	<i>Anke Huth</i>